







Approccio Meccatronico alla progettazione

Ing. Roberto Loce
Solution Architect Motion Control
Rockwell Automation









Una moderna macchina automatica è un sistema meccatronico

Meccanica

- Organi di trasmissione
- **Elementi Strutturali**
- Riduttori
- Sistemi di Guida
- Assi

Elettronica

- Controllo ad anello aperto
- Drives
- Motori
- Sistemi Retroazion





- HMI: Human Machine Interface
 - Control software
 - CNC
 - Motion Contr
 - PLC
- Controllo anello chiuso




Approccio meccatronico



Meccatronica: approccio interdisciplinare all'interazione ed integrazione tra meccanica, elettronica ed informatica.

Collaborazione in cui si integra la conoscenza tecnologica specifica del costruttore con la competenza applicativa del fornitore di soluzioni di automazione.

- per ottimizzare le soluzioni ed eseguire analisi dettagliate su macchine esistenti;
- Per supportare lo sviluppo di nuove macchine con la simulazione meccatronica considerando l'interazione e integrazione di tutti i vari componenti, dagli organi di trasmissione ai sistemi servocontrollati.






Ottimizzare l'intero processo di progettazione








Il nuovo impianto o macchina può essere testato e validato durante la fase di simulazione senza dover realizzare alcun prototipo

Un prototipo virtuale consente di ridurre tempi e costi










Progettazione Integrata














Progettazione Integrata



• Il tool di selezione dei componenti interagisce con l'ambiente di progettazione CAD per ottimizzare gli aspetti più problematici dell'applicazione; il risultato finale è la legge di moto più adatta alle scelte fatte da implementare direttamente nel programma del controllore.

Tool di Ottimizzazione


Analisi rendimento del sistema Permette di esaltare le prestazioni della macchina e ridurre il consumo energetico. - Analisi delle tolleranze del sistema
Permette di verificare quanto una
macchina sarà insensibile alle
modifiche dei dati iniziali

Analisi stop di emergenza. Aiuta a massimizzare la

produzione senza compromettere la sicurezza



- Modello termico del sistema Utile per OEM che esportano verso paesi dei climi caldi.



- Analisi del riduttore Guida i progettisti ad una soluzione ottimizzata



Analisi tolleranza sulla tensione di alimentazione Riduce il rischio di problemi sul campo che richiedono alti costi di supporto.



- Tuning simulato del sistema
Aiuta a ridurre gli errori di
progettazione ed a risparmiare
tempo in fase di messa in funzione.



Dimensionamento di attuatori integrati con stima della vita e pianificazione della manutenzione.










Sviluppo congruo ed efficace









CAD meccanico

- Progettazione
- Motion Analisys
- Plot diagramm di forza

Tool Simulazione

- Analizza
- Simula
- Ottimizza
- Seleziona

PLC Macchina

- Export / Import
- AOI instruction
- CAM Profile

Sviluppo congruo ed efficace Edit View Insert Tools Window Help 🔉 Two Axis Linear_Modificato_3.SLDASM * ? - - B X Insert Linear Move Assembly Reference Show Bill of Instant3D Mate Smart Exploded Components Compon... Component Features Geometry Hidden Fasteners Motion Materials Components Study Assembly Layout Sketch Evaluate Office Products Q Q 😽 🛍 🕮 + 🗇 + 🚱 + 🕒 + **9** 😭 🐕 🌉 👣 Two Axis Linear_Modificato_3 (Default<<Defaul 🔨 🗓 🥝 Sensors Annotations 🛓 👱 Lights, Cameras and Scene 🔆 Front Plane 🔆 Top Plane 🔆 Right Plane A Origin ▼ Trans Veloc - X-LinearMotor15 *Front 0.3 ▽ かかか × × 0.0 0.0 🔨 🖃 😘 Two Axis Linear Modificato 3 Norientation and Camera V 🗓 💹 Lights, Cameras and Scen Gravity 0.00 0.36 0.73 1.09 1.45 1.82 2.18 2.55 2.91 3.27 3.64 0.00 0.36 0.73 1.09 1.45 1.82 2.18 2.55 2.91 3.27 3.64 LinearMotor15 Time (sec) Time (sec) LinearMotor16 ± 😘 (f) Backplane<1> (Default ×)Ort Force - X-LinearMotor15 ⊕ Sracket<2> (Default<<De </p> (Liotwa 74 ★ Shoulder<1> (Default<<C) </p> ★ P Arm1<1> (Default<Default) </p> iion 53 × ⊕ % Bracket<1> (Default<<De </p> 9 33 E 12 ★ Shoulder<2> (Default<<C) </p> ★ P Arm1<3> (Default<Default) </p> 0.00 0.36 0.73 1.09 1.45 1.82 2.18 2.55 2.91 3.27 3.64 0.00 0.36 0.73 1.09 1.45 1.82 2.18 2.55 2.91 3.27 3.64 ± \$\mathbf{\text{P}} \text{ Arm1<2> (Default<Default Time (sec) Time (sec) ± 🦠 Knee<1> (Default<<Defau ⊕ 🤏 (-) Hand<1> (Default<<D 🗾 > Model Motion Study 1 Motion Study 2 SolidWorks Premium 2010 Under Defined Editing Assembly

Sviluppo congruo ed efficace PHELW Lines **Solid** Works - 8 × Insert Mate Nation Analysis Components Component Assembly Layout Sketch E ₽× **9** 😭 🐕 <u>6</u> 🌃 🌇 Two Axis Linear_Modificato_3 🕳 🙋 Sensors Annotations 🛓 👱 Lights, Cameras and Scene 🔆 Front Plane 🔆 Top Plane Maria District Contract Con 🔆 Right Plane A Origin □ 🔨 🖃 🧐 Two Axis Linear Modific Orientation and Cam 🛓 👱 Lights, Cameras and Gravity 3.27 3.64 🔀 LinearMotor15 🔀 LinearMotor16 ⊕ ♥ (f) Backplane < 1 > (C) ×)Ort ⊕ S Carriage < 1 > (Defau Mutur: MPL-8540K ⊕ ¶ Bracket<2> (Default) Shows below is the ratio analysis chart for year application and the sale Use the option bins provided as the right to analyse exitations. ★ Shoulder < 1 > (Defau Max. Application Motor Opend 1145.872 rpm Max. Acestome Rights 7.645 Transcription | Hallo | 1,000 Interfess National Plaks | 1,000 ilon ★ S Carriage < 3 > (Defau) ⊕ Shacket<1> (Default) Bracket<1> (Default) Bracket<1 (D ★ Shoulder<2> (Defaul) 3.27 3.64 ♠ ♥ Arm1<2> (Default<) </p> ± % Knee<1> (Default<√ ⊕ 💖 (-) Hand<1> (Defau Model Motion Stud SolidWorks Premium 2010 Peak Torque Analysis Segment Load Any discovery in the same of percentages in the tempology of to the absolute value Help Provenger storm on distinguish against the highlaster Feet Tenan

Sviluppo congruo ed efficace Solid Works Insert Mate Components Profile Export Wizard AOI CG 04 INDEX Equal Start End Slope Type of Exports Controller HOTT AOLCG_01_START_NEW_CAM_AOLCG_01[5] -(EN)--AOI_CG_04_INDEX_Equal_Start... AOI_CG_04[5] ... H(EN)-Controller Ta Inp Start Slope Cfg Move Type AOI CG Move Type Incremental Controller Fa <ER>-Power-Up Ha Inp_Master_Start_Position Inp_Master_Position 0.0 1.0 Select the desired type of Export from the fol 🖹 🛅 Tasks (PC)-☐ MainTask Inp_Slave_Start_Position 0.0 Inp_Slave_Position 2.75 ☐ MainProg Ref AOI CG AOI CG Cfg_Velocity_Form_Factor 1.5 Progr Logix CAM Profile Editor Main! Cfg_Accel_Jerk_percent_Time 40.0 AOL Logix Ladder AOI Instructions Cfg_Decel_Jerk_percent_Time 40.0 CAM CAM Cfg Maximum Slope 9999999 SolidWorks Motion Study Move Profile Unscheduled Motion Groups Cfg_Minimum_Slope 9999999 User Defined CAM_Group Rpt_Segment Axis 1 Rpt ERR Profile generated as AOI instructions to exp Ungrouped A Ref_AOLCG AOI_CG ladder. Add On Instructions (AOI) are requir - Add-On Instructions AOI_CG_01 AOI CG 02 AOI CG 02 CRUISE or DWELL--AOI_CG_04_INDEX_Equal_Start_End_Slope-AOI_CG_03_ < Back Next > AOI_CG_02_CRUISE_or_. AOI CG_04_INDEX_Equal_Start... AOI_CG_04[6] ... M AOI_CG_04_ AOI_CG_02[5] <(EN)— Cfg_Move_Type AOI_CG.Move_Type_Incremental Cfg_Move_Type AOI_CG.Move_Type_Incremental AOI_CG_05_ (ER)-(ER)-± \$\Pm\1<2> (Default<| AOI_CG_06_ Cfg Define AOL CG.Define_MP Inp Master Position 1.0 ★ % Knee<1> (Default<・) </p> AOI CG 12 (PC)--(PC)-🛓 🤏 (-) Hand<1> (Defau AOI_CG_15_ Inp_Master_Position 0.5 Inp_Slave_Position 2.75 Model Motion Study ☑ AOI_CG_99_ Inp_Slave_Position Cfg_Velocity_Form_Factor 0.0 1.5 SolidWorks Premium 2010 Data Types User-Defined Rpt_Segment Cfg_Accel_Jerk_percent_Time 40.0 Peak Torque Analysis Strings . Rpt ERR Ref AOI CG AOI CG Add-On-Defit Cfg_Decel_Jerk_percent_Time 40.0 Predefined Cfg_Maximum_Slope 9999999 Help: Provenger storm on distinct agent the highway five Torque Return

Benefici e vantaggi competitivi



- → Tempi di sviluppo e di introduzione sul mercato (time to market) notevolmente ridotti;
 - → Verifica e validazione senza rischi di nuovi e creativi concetti di macchina (ad es con Direct Drives) maggior potere innovativo
 - → Conseguimento sicuro degli obiettivi di progetto: progettazione Goal oriented;
 - → Elevata affidabilità durante lo sviluppo;
 - → Prototipo Virtuale: Individuazione rapida e correzione di eventuali punti critici già in fase di progettazione;
 - → Risparmio economico, con riduzione dei costi ed ottimizzazione delle risorse;
 - → Macchina già altamente ottimizzata e performante e quindi tempi di messa in servizio ridotti;
 - → Aumento di produttività e qualità fin dal principio con sicura soddisfazione del cliente finale.



- Richiesta di prestazioni sempre maggiori
- Massimo sfruttamento delle macchine
- Controllo della produzione
- Lotti di produzione più piccoli
- Elevata qualità del prodotto finale
- Affidabilità elevata e costi di gestione/manutenzione ridotti
- Collegamento e scambio dati tra macchine
- Maggiore attenzione alla sicurezza
- Riduzione costi



Esigenze costruttori di macchine



- Flessibilità e scalabilità dei sistemi
- Facilità d'utilizzo e di integrazione
- Prestazioni elevate
- Tempi e costi di sviluppo
- Affidabilità elevata e costi di gestione/manutenzione ridotti
- Nuovi concetti di macchina, automazione sempre più spinta, azionamenti elettrici
- Meccatronica come valido supporto per ottimizzazione, analisi e simulazione

